



Passion to Innovate.  
Power to Deliver.

## STC Information Sheet

**FAA STC:** ST02401AT

**Master Drawing List:** 344HO173-MDL

**Aircraft:** Boeing B737-600/-700/-800 Series Aircraft

**Configuration:** 1

Honeywell TCAS II and Dual Mode S Retrofit

**Mod. Order:** ASIG-010M-1

**AFMS:** 344HO173-FMS

**Master Kit List:** N/A

**ICA:** 344HO173-CAW

### Summary:

The Honeywell Traffic Alert and Collision Avoidance System (TCAS II) and Dual Mode S retrofit replaces the existing Rockwell Collins TCAS II and Dual Mode S systems with equivalent Honeywell systems. There is no other aircraft modification beyond replacement of the applicable LRUs.

### Notes:

For aircraft delivered with Rockwell Collins TCAS equipment

### Material List

| QTY | Part Number    | Description            | Source/MFGR |
|-----|----------------|------------------------|-------------|
| 1   | 066-50000-2220 | TCAS Processor         | Honeywell   |
| 2   | 066-01127-1601 | ATC/Mode S Transponder | Honeywell   |
| 2   | 071-50001-8102 | Directional Antenna    | Honeywell   |
| 1   | 071-01503-2601 | TCAS/ATC Control Panel | Honeywell   |